

<b>Search Notes</b>	<b>Application/Control No.</b>	<b>Applicant(s)/Patent Under Reexamination</b>
	10596034	BASSIN, DAVID
	<b>Examiner</b> LAToya LOUIS	<b>Art Unit</b> 3771

### SEARCHED

<b>Class</b>	<b>Subclass</b>	<b>Date</b>	<b>Examiner</b>
128	204.22	11/20/2009	L.L.
128	204.22	3/10/2010	L.L.
Update	Updated Above Search	10/28/2010	L.L.
128	200.24, 204.18, 204.21, 204.23, 204.25, 204.26, 204.28, 204.29, 205.11, 206.21	10/28/2010	L.L.

### SEARCH NOTES

<b>Search Notes</b>	<b>Date</b>	<b>Examiner</b>
Searched with terms (error, ventilator, fast, slow dead space, clipped integral in subclasses 128/200.24, 204.18, 204.21, 204.23, 204.25, 204.28, 205.11, 206.21, 204.26, 204.29 (Consulted Annette Dixon AU 3771 for subclasses to search)	11/20/09- 11/23/09	L.L.
Text Search EAST (error, ventilator, fast quick slow, fuzzy logic)	11/20/09- 11/23/09	L.L.
Inventor Search (David Bassin)	11/23/2009	L.L.
NPL Searched Google (Ventilator and slow response)	11/20/09- 11/23/09	L.L.
Reviewed International Search Report for PCT/AU2004/001651	11/20/2009	L.L.
Text Searched Google	10/28/2010	L.L.

### INTERFERENCE SEARCH

<b>Class</b>	<b>Subclass</b>	<b>Date</b>	<b>Examiner</b>